

30a ultrapure > water OUT ultrapure water IN = <u>12</u> 3 


F / G. 2




F / G. 3




F / G. 4











F / G. 7




rotational speed (rpm)


F / G. 8




F / G. 9




F / G. 10






F/G. 12



F / G. 13



F/G.14

